Form: rorocess

Wednesday, 6/20/2007 11:21:26 AM Date: Kim Johnston User. **Process Sheet** : FWD X-TUBE : CU-DAR001 Dart Helicopters Services **Drawing Name** Customer : 33022 Job Number : 10006 **Estimate Number** : D2889 Part Number : NA P.O. Number S.O. No. : NA · D2889 REV B : 6/20/2007 **Drawing Number** This Issue : N/A : NC Project Number Prsht Rev. : NIA : LANDING GEAR **Drawing Revision** First Issue : 31367 Material Previous Run Each : 6/27/2007 Qty: 1 Um: **Due Date** Written By Checked & Approved By 05-10-25 JLM New Issue Comment **Additional Product** Job Number: Description: **Machine Or Operation:** Seq. #: Crosstube material D6005180 1.0 Comment: Qty.: 1.0000 Each(s) 1.0000 Each(s)/Unit Total: Crosstube material Pick: Batch Qty Part number Description 25673 Fwd Crosstube 1 D2889 BENDING BENDING MACHINE 2.0 Comment: LANDING GEAR RESOURCE 1 1-Bend D2889 as per Dwg D2889 and Folio FT001 7-6-26 LANDING GEAR RESOURCE 1 LANDING GEAR 1 3.0 Comment: LANDING GEAR RESOURCE 1 1-Deburr and Polish 4.0 QC6 DIMENSIONAL CHEC Comment: DIMENSIONAL CHECK HAND FINISHING RESOURCE 5.0 Comment: HAND FINISHING REŞOURCE #1 Acid etch and alodine as per QSI 005 4.1 Inside and outside of tube

Page 1

## **Dart Aerospace Ltd**

W/O:		WORK ORDER CHANGES								
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
<u></u>										
· 										
Part No	):	PAR #: Fault Category:	NCR: Yes	No DQ	A: <u>~</u>	Date: <u>C</u>	HOHOY			

QA: N/C Closed: \_\_\_\_ Date: \_\_\_\_

NCR:			WORK ORDER NON-CONFORMANCE (NCR)							
		Description of NC	Corrective Action Section B		Varification A					
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspector		
			-							
							I			

NOTE: Date & initial all entries

Date:

Wednesday, 6/20/2007 11:21:26 AM

Ûser:

Kim Johnston

**Process Sheet** 

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: FWD X-TUBE

Job Number: 33022

Part Number: D2889

Job Number:



Seq. #:

Machine Or Operation:

Description:

6.0

QC3

INSPECT POWDER COAT/CHEMICAL CONVERSION





Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and Stock

Location: W/O

32940

8.0

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



## **Dart Aerospace Ltd**

W/O:		WORK ORDER CHANGES									
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
•						:					
Part No	: <u> </u>	PAR #: Fault Category:	NCR: Y	es No DC	A:	Date: _					


QA: N/C Closed: \_\_\_\_ Date: \_\_\_\_

NCR:		V	WORK ORDER NON-CONFORMANCE (NCR)						
		Description of NC	Corrective Action Section B			Verification	A	Annrova	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspecto	
						:			

NOTE: Date & initial all entries


DART AEROSPACE LTD		Work Order:	33022
Description: Crosstube Fwd	·	Part Number:	D2889
Inspection Dwg: D2889	Rev: B		Page 1 of 1

Required Dimension	Min	Max
Height	49.875	50.125
1/2 Span	69.275	69.525
Angle	49	52
Total Span	138.55	139.05



	mments		
Tube was cut fer "	01 B	32940	
			·
		<u> </u>	
		/	
QC15 Inspection		/ OSTOY	
Date		5 m	

Rev	Date	Change	Revised by	Apprøved
A	07.02.06	New Issue	KJ/JM	m
			()	<b>/</b> .



, , .					
*				<i>y</i>	· · · · · · · · · · · · · · · · · · ·
	• <u>•</u> • <u>•</u> • <u>•</u>			•	
					٠.
ź.	a the letter of the same and the	Control of the second	eren eren eren eren eren eren eren eren		<b>e</b> r €